



Proposed Code Change  
State Form 41186R

RETURN TO:  
INDIANA DEPARTMENT OF HOMELAND SECURITY  
CODE SERVICES SECTION  
302 W. Washington Street Room W246  
Indianapolis, IN 46204

FOR OFFICE USE ONLY

Received 8/11/09

Code 19.2-09

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY – Dashed line through material to be deleted, underline material to be added)

Use second sheet for any material requiring more space.

Code Title 2009 Indiana Residential Code		Edition First Edition
Section number and title R302.8, Protection of floor framing components.		Page 1 of 4
Proponent Craig Wagner	Title Chief Building Inspector/ IABO Code Comm. Member	
Address 220 W Van Buren St, Columbia City IN 46725		Phone 260-248-3111
PROPOSED CODE CHANGE (Check One)		

☐ Change to read as follows    ☐ Add to read as follows    ☒ Delete and substitute as follows    ☐ Delete without substitution

~~**R302.8 Foam plastics.** For requirements for foam plastics see Section R316.~~

**R302.8 Protection of floor framing components.** Floor systems within dwelling units that are constructed using wood I-joists, steel plated wood trusses, wood trusses manufactured with steel bar or pipe webbing, cold formed steel joists or cold formed steel trusses shall be protected on the underside by a minimum 1/2-inch (12.7 mm) gypsum board applied in accordance with Section R702.3.

**Exceptions:**

1. Crawlspace where the maximum clear height from the underside of the floor joists to the crawlspace floor is 3 feet or less and is not intended for mechanical equipment use or storage.
2. Floors in which the exposed components are protected by listed materials installed to provide a 30 minute fire-resistive rating in accordance with ASTM E119 or UL 263.

REASON AND FISCAL IMPACT

Wood I-joists, floor trusses and cold-formed steel floor members are widely used in the residential construction industry. The engineered components offer many advantages to homeowners and contractors such as straightness, reduced weight and longer spans. However some of the advantages can turn into disadvantages if the structure is involved in a fire. The thin profile of I-joists allow the members to burn through faster and the long spans often result in catastrophic collapse of entire floor systems. Metal plate connected trusses can collapse when the wood that the plates are clamped into burns away, and cold-formed metal joists are subject to collapse from the heating of a fire below. The result is partial or complete collapse resulting in complete loss of the structure. Several national advisory groups have issued statements proposing some form of protection for these floor systems that would provide more time for fire service to

complete rescue efforts and attack the fire before the point of collapse is reached. In a recent fire in my area the structure completely collapsed into the basement and because of the intense heat of the fire the entire structure, including the footings, had to be replaced. This issue has received attention from several firefighter groups and I am aware of at least one Indiana firefighter lost in a fire from collapse of wood I-joists. This proposal is fashioned after a proposal to ICC by a member of the Cleveland, Ohio, fire service Sean DeCrane. I have included his reason below.

On August 13, 2006 a Wisconsin fire fighter was killed, and a second fire fighter injured, when the floor they were operating on collapsed sending them into the basement. One fire fighter fell directly into the room of origin and was killed, the second fire fighter landed on the opposite side of a block wall and survived by shielding herself and making an escape through a rear window. They checked the floor to ensure it was safe and solid, just prior to collapse they heard a loud crack. T

The floor they were operating on was unprotected lightweight construction that collapsed without warning. In the ensuing investigation, the National Institute for Occupational Safety and Health released report F2006-26<sup>1</sup>. One of the recommendations is to “modify current building codes to require that lightweight trusses be protected with a fire barrier”. This should not only pertain to truss construction. There are additional forms of construction that can be determined to be lightweight, cold form steel, bar joists, wooden engineered I-beam, etc., the recent trend in residential construction is to use products that are financially beneficial. It is the belief of many of us in the fire service that as the industry engineers products to a more finite point we are losing our safety factors.

In their report 2007-12 released May 16, 2008, NIOSH<sup>2</sup> recommended “Ensure fire fighters are trained for extreme conditions such as high winds and rapid fire progression associated with lightweight construction”. They further stated, “In this era of new lightweight construction, training procedures covering strategy and tactics in extreme operations conditions, such as high winds and lightweight building construction (i.e. materials and design) are needed for all levels of fire fighters. Lightweight constructed buildings fail rapidly with little warning, complicating rescue efforts. The potential for fire fighters to become trapped or involved in a collapse may be increased. There are twenty-nine actions for fire fighters can take to protect themselves when confronted with buildings utilizing lightweight building components as structural members. They range from looking for signs or indicators that these materials are used in buildings (such as, newer structures, large unsupported spans, and heavy black smoke being generated) to getting involved in newer building code development”.

On September 27, 2007 NIOSH released report 2006-24<sup>3</sup>. The first recommendation of the report read “Ensure that fire fighters and incident commanders are aware unprotected pre-engineered I-joist floor systems may fail at a faster rate than solid wood joists when exposed to direct fire impingement, and they should plan interior operations accordingly”. The discussion of the recommendation is quite lengthy but identifies the advantages of the construction industry using this type of construction but also relates the dangers to fire fighters, “The Illinois Fire Service Institute, at the University of Illinois, conducted tests to help determine the structural stability of sample floor systems. These studies suggest that engineered wooden I-beams can fail

in as little as 4 minutes and 40 seconds under controlled test conditions”. The report also states that weakened floors are difficult to detect from above as the floor surface may appear intact.

On November 16, 2007, NIOSH released report F2007-07<sup>4</sup>. In this Fire Fighter Death in the Line-of-Duty report, NIOSH recommends “building code officials and local authorities having jurisdiction should consider modifying the current codes to require that lightweight trusses are protected with a fire barrier on both the top and the bottom”. The report further states “In this incident, the floor trusses for the first floor did not have any protection on the bottom cord, which immediately exposed the trusses to fire in the basement. Unfinished basements are very common throughout the country. Basements typically house additional fire exposures such as alternative heating sources, hot water heaters, clothes dryers, etc.. It is critical for trusses and lightweight engineered wood I-beams that are used in a load-bearing assembly to be protected with a thermal barrier such as gypsum wallboard. The function of the thermal barrier is a critical factor in the fire performance of the assembly”.

In April, 2005, NIOSH released their report “Preventing Injuries and Deaths of Fire Fighters due to Truss System Failures”<sup>5</sup>. In their release they recommended the placement of a labeling system on buildings to indicate the type of construction. While this recommendation will probably not be acceptable to residents of a one or two family home, we can mandate that they increase the protection of the construction type to provide increased safety to the residents and the responding fire fighters.

In fact, NIOSH has been concerned enough with the performance of lightweight floors in fire conditions they released a Workplace Solutions report in February, 2009, *Preventing Deaths and Injuries of Fire Fighters Working Above Fire-Damaged Floors*<sup>6</sup>. Authors of the report recommend “Builders, contractors, and owners should consider protecting all floor systems, including engineered wood I-joists, by covering the underside with fire-resistant materials”.

Many of the opponents of this requirement have made claims that the fire service has failed to provide technical data to support our real world experiences with the lightweight products. Since the previous ICC code cycle there have been three specific reports released by three separate test groups performing tests for different reasons. I have included their results below.

The National Research Council Canada performed a series of tests in creating their report Fire Performance of Houses, Phase I: Study of Unprotected Floor Assemblies in Basement Fire Scenarios, released December 18, 2008. The goal of the report was “With the advent of new materials and innovative construction products and systems for use in construction of houses, there is a need to understand what impacts these materials and products will have on occupant life safety under fire conditions and a need to develop a technical basis for the evaluation of their fire performance”.<sup>7</sup> These tests were not intentionally conducted for fire fighter safety but rather to identify the dangers to the civilian occupants and their ability to self evacuate. The report states “With the relatively severe fire scenarios used in the experiments, the times to reach structural failure for the wood I-joist, steel C-joist, metal plate and metal wood truss assemblies

---

<sup>6</sup> National Institute for Occupational Safety and Health Workplace Solutions, *Preventing Deaths and Injuries of Fire Fighters Working Above Fire-Damaged Floors*, February, 2009.

<sup>7</sup> National Research of Canada, *Institute for Research in Construction; Fire performance of Houses, Phase I, Study of Unprotected Floor Assemblies in Basement Fire Scenarios*, December, 2008.

<sup>8</sup> Tyco Industries, *A Technical Analysis: The Performance of Composite Wood Joists Under Realistic Fire Conditions*, September 2008.

<sup>9</sup> Underwriters Laboratories, *Structural Stability of Engineered Lumber in Fire Conditions*, September 30, 2008

were 35-60% shorter than that for the solid wood joist assembly". Additionally, "For the solid wood joist assemblies, the structural failure occurred after deflection of the floor, mainly in the form of OSB sub-floor failure (burn through). For all other floor assemblies, after deflection of the floor, the structural failure occurred either in the form of complete collapse into the basement or in the form of a "V" shaped collapse due to joist or truss failure". In keeping with the intent of occupant safety the report also found "One engineered floor assembly, which gave the shortest time to reach structural failure in the open basement scenario, failed structurally in the closed basement doorway scenario before the tenability limits were reached for healthy adults of average susceptibility". This calls into question, if it can not give the occupant time to self evacuate how will it perform when a fire fighter is performing Search and Rescue for that specific occupant. In summarizing the various test results the report found "The time gap between the onset of untenable conditions and the structural failure of the floor assembly was smaller for the engineered floor assemblies than for the solid wood joist assembly used in the experiments". This is very serious for the responding fire fighter performing life saving Search and Rescue for occupants who have lost consciousness due to the untenable conditions. These victims may still be savable but, the performances of the lightweight assemblies indicate that, savable victims may not be reached due to floor compromise.

In 2008 Tyco Fire Suppression & Building Products performed a series of fire tests. The intent of these tests was to demonstrate the impact residential sprinklers will have in improving fire safety in one and two-family occupancies when lightweight construction is present. The results of these tests were released in 2008 as A Technical Analysis: The Performance of Composite Wood Joists Under Realistic Fire Conditions.<sup>8</sup> In the introduction of the report the author states, "One example of the difference in fire performance of a lightweight structural member compared to solid sawn lumber is the behavior of composite wood joists. When a composite wood joist is exposed to fire, the thin oriented strand board used as the web in the joist is quickly consumed, which results in an inability of the joist to carry the load and ultimately a failure of the supported floor assembly". Later in the introduction the report continues "Due to the greater mass per unit of surface area of the solid wood joist, it will support the floor assembly for much longer than its lightweight alternative when exposed to equivalent fire conditions". The first test involving an un-sprinklered room fire led to flashover in 7:09 from ignition and floor assembly collapse at the 11:30 mark from ignition. That is roughly four minutes from flashover we had a collapse of almost the entire 16' x 16' floor area. The second test results reached flashover in only 5:15 from ignition, collapse in this test occurred at 8:34 from ignition, a stunning three minutes after flashover. This would be the time the fire fighters are entering the structure for suppression and Search and Rescue efforts.

These reports are still not enough for some critics so I am referencing a third report. Underwriters Laboratories, The Chicago Fire Department and the International Association of Fire Chiefs received a grant from the Department of Homeland Security to conduct a number of tests on various topics but the main issue was to conduct tests, and report the findings, to evaluate the performance of lightweight structural components when exposed to fire and if the components can be protected. They recently issued the subsequent report *Structural Stability of Engineered Lumber in Fire Conditions*.<sup>9</sup> Tests assemblies were subjected to the standards of the ASTM E119 Test Standard. Two assemblies did not include a ceiling, six of the assemblies included a ceiling consisting of ½ inch thick gypsum board and one assembly included a ¾ inch plaster ceiling. A load of 40 psf was placed along two of the four edges and two 300 lb fire fighter mannequins were applied to the floor assembly. Results from the tests indicated that

unprotected 12” wooden I-joist reached structural failure at the 5:58 mark in the tests. The resulting failure covered a large area of the floor. The unprotected 2” x 10” wooden I-beams reached structural collapse at the 18:45 mark in the test, a difference of over twelve minutes. These twelve minutes are critical in Search and Rescue. Further tests demonstrated that when ½ inch gypsum was placed on the 12” I-joists the collapse did not occur until the 26:45 mark in the test. Just a simple ½ covering extended the collapse time approximately twenty minutes. When the ½ inch covering was applied to the wooden I-beams the collapse time was extended to 44:45 mark in the test.

1. National Institute for Occupational Safety and Health Report F206-26. July, 2007.
2. National Institute for Occupational Safety and Health Report F2007-12, May, 2008.
3. National Institute for Occupational Safety and Health Report F206-24, September, 2007.
4. National Institute for Occupational Safety and Health Report F2007-07, November, 2007.
5. National Institute for Occupational Safety and Health Alert, “Preventing Injuries and Deaths of Fire Fighters due to Truss System Failures”.
6. National Institute for Occupational Safety and Health Workplace Solutions, *Preventing Deaths and Injuries of Fire Fighters Working Above Fire-Damaged Floors*, February, 2009.

**Fiscal impact:** (I have not had time to complete fiscal impact on this item)

REVIEW RECOMMENDATION
Approve
Disapprove
Approve as amended
Further Study